



ST. ANTHONY OF PADUA PARISH

Okeene, Oklahoma

The windows at St. Anthony of Padua Parish had a number of bulges and broken stained glass pieces. Following restoration of the windows, including replacing broken pieces and flattening bulges, the windows were covered in new protective covering using a white, vented perimeter frame.



