



FIRST BAPTIST CHURCH

Nashville, Tennessee

After uncovering five stained glass windows in the chapel of First Baptist Church of Nashville, the windows were in need of professional cleaning and protective covering. The stained glass had rust problems on the interior, but after the professional cleaning they shine brightly and are rust-free.

“We are very pleased with the work... The inside sparkles and the outside looks richer, darker, and cleaner.”

*- Allen Adcox,
Business Administrator*





American
CONSULTATION ON STAINED GLASS

Kelly@AmericanStainedGlass.org
www.AmericanStainedGlass.org
254.717.8283