




# WYNNTON UNITED METHODIST

## *Columbus, Georgia*



*The clouded polycarbonate at Wynnton United Methodist Church was not only unattractive from the exterior, it was blocking sunlight and left the sanctuary feeling dark.*

*After a successful fund raising effort, the church moved forward in replacing the old protective covering with a new tempered glass.*





*Right: A discreet venting system was used in the frame work to allow heat to escape*



*American*  
CONSULTATION ON STAINED GLASS

Kelly@AmericanStainedGlass.org  
www.AmericanStainedGlass.org  
254.717.8283